

Resilience Sub group Notes for CC Meeting 2.4.2025

1. Fife Council's Leaky dams recommendation : landowners have been contacted.
2. Resilience measures:
 - a) House holders continue to refine the measures in place
 - b) New Hedging and trees have been planted alongside the road above Brunton
3. Culvert survey and repair : Another company is considering surveying the culvert.
4. SEPA have now issued Surface Water and Small Watercourse Flood Maps
5. Building a response to power cuts :. Luthrie Village Hall welcomes the idea of a being the location for a warm space. They have asked for a written proposal which is in process.